



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

July 7, 2010

Reviewed: PRB

Mine Name: RDS 502
Operator Name: West Desert Granite L.C.

Permit number: M0230067
Inspection Date: 06/24/2010
Time: 12:15-12:45 PM

Inspector(s): Wayne Western,
Other Participants: None
Mine Status: Ina

Weather: Clear skies 80's

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds, Permit Fees
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Soils
9. Revegetation
10. Other

Evaluated Comment Enforcement

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The purpose of the inspection was to conduct an annual inspection of a large mine.

Inspection Summary:


The RDS mine is inactive. The Permittee posted a bond for \$33,250. The Permittee stated in the 2007 and 2008 annual reports that no activities had occurred at the site.

The inspectors did not find any evidence that mining or reclamation activities had recently taken place. There are some small trenches that were dug to access the granite and there are boulders that have been split.

There are mounds of soil that appear to be stockpiled topsoil. There are no signs of erosion. The site appears to be stable.

Conclusions and Recommendations:

Inspector's Signature



Directions:

Directions to Site: West of the Delta power plant in the Desert Mountains

Go the Delta power plant, turn right, and head to Desert Mountain where the mine sits on the South side of the mountain.

The site can also be accessed by going on the Weis highway (well maintained dirt road) and turning south on the Desert Mountain Road. Mine is east of the Desert Mountain Road and can be seen from the road.

whw:pb

CC: Jerry Mansfield, BLM
George Finnegan

O:\M023-Juab\M0230067-RDS502\inspections\InspM0230067_05142009I.doc



Access road



Stockpiles